State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor

Governor

1594 West North Temple, Suite 1210
PO Box 145801

Governor
Kathleen Clarke
Executive Director

Governor
Salt Lake City, U
801-538-5340

Lowell P. Braxton Division Director Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD) Partial: XXX Complete: Exploration: Inspection Date & Time: 5/9/2000 / 7:30a.m.-3:40p.m.

Date of Last Inspection: 4/5/2000

Mine Name: SUFCO Mine County: Sevier Permit Number: ACT/041/002						
Permittee and/or Operator's Name: Canyon Fuel Company						
Business Address: 397 South 800 West, Salina, Utah 84564						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Wes Sorensen, Mike Davis						
State Officials(s): Peter Hess, Mary Ann Wright Federal Official(s): None						
Weather Conditions: Warm, 70's, Partly Cloudy						
Existing Acreage: Permitted-17621.29 Disturbed-70.189 Regraded- Seeded- Bonded-70.189						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/_ Temporary Cessation/_ Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL	EVALUATED [XX] [XX] [XX]	<u>N/A</u> ∐ ∐ ∐	COMMENTS [XX] []	NOV/ENI
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	\Box		\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	$\overline{[XX]}$	\Box	\Box	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	[XX]		[XX]	\Box
d.	WATER MONITORING	\square	\Box	\Box	
e.	EFFLUENT LIMITATIONS	$\overline{\square}$	\Box	\Box	
5.	EXPLOSIVES	\Box	\Box	\Box	
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES				
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]		[XX]	
8.	NONCOAL WASTE	[XX]		\Box	\Box
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES			\Box	\Box
10.	SLIDES AND OTHER DAMAGE		[XX]		\Box
11.	CONTEMPORANEOUS RECLAMATION	. []	[XX]		
12.	BACKFILLING AND GRADING		[XX]		\Box
13.	REVEGETATION		\Box	\Box	\Box
14.	SUBSIDENCE CONTROL		\Box	\Box	· <u> </u>
15.	CESSATION OF OPERATIONS		[XX]	\Box	\Box
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	\Box	\Box	\Box
b.	DRAINAGE CONTROLS	[XX]	\Box		\Box
17.	OTHER TRANSPORTATION FACILITIES	\Box	\Box		\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	\Box	[XX]	
19.	AVS CHECK (4th Quarter-April, May, June)(date)			\Box	\Box
20.	AIR QUALITY PERMIT		LĪ.	\Box	\Box
21.	BONDING & INSURANCE	\Box	Ll	$\bar{\Box}$	

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/041/002

DATE OF INSPECTION: 5/9/2000

(Comments are Numbered to Correspond with Topics Listed Above)

Note: Ms. Mary Ann Wright, Associate Director of Mining, UDNR/OGM attended today's partial inspection of the SUFCO Mine surface facilities area. No notices of violation were issued as a result of today's inspection. The Mine site received .81 inches of rain during the previous 27 hour period.

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Prior to convening the field inspection, Mr. Wes Sorensen, Manager of Tech Services and Mr. Mike Davis discussed a problem which had arisen with the 160 acre IBC (ACT/041/002-IBC99C) which has been approved under a "right of way" procedure to allow development mining in that area.

In order to avoid an archaeological site (a rock shelter) the permittee is proposing to alter the directional bearing upon which the three entry Pines Bleeder section will be developed. This will cause the #3 entry (extreme right hand entry) to intercept and cross the approved IBC boundary at crosscut 26. The entry projection develops a wedge approximately three thousand feet long and tapers from a zero width to a maximum eighty foot width. This equates to 2.75 additional acres.

In order to avoid shutting down the development of these bleeders, the permittee needs one of two approvals:

- 1) a DOI finalized approval for the Pines Tract by August 7, 2000, or
- 2) an approved contingency plan which would allow them to cross the original IBC boundary and develop the additional 2.75 acres. This involves a rapid interagency analysis and approval.

4c. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The silt fences located on the ESE side of the main substation were inspected. The amount of grasses present upslope of one of the fences is adequate to allow the removal of that fence. Mr. Davis noted this; it was decided that other fences in this same general area should remain.

A fence directly in front of the main substation's steel bin wall has thinning fabric; same should be replaced to return that fence to full function.

The silt fence on the west side of the steel bin wall has been repaired.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

As noted today, previous end-dumped piles located on the active lift have been leveled and cleaned of noncoal waste materials. The SUFCO site is one which will be evaluated in the near future for reclamation success by the UDNR/OGM//OSM evaluation team.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/041/002

DATE OF INSPECTION: 5/9/2000

(Comments are Numbered to Correspond with Topics Listed Above)

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

As noted during today's inspection, the construction work for the new Link Canyon substation facility was about 98% complete. Disturbed area perimeter markers were in place as was the permittee identification sign. A chain link fence with gates was in place to prohibit unauthorized access. Utah Power and Light inspectors were on site to evaluate the job; the permittee is hoping to energize the substation this week.

The reclamation of the original site is postponed until adequate clearances for the raptor nesting periods are obtained.

Copy of this Report:

Mailed to: Mike Davis (Canyon Fuel)

Given to: Pam Grubaugh-Littig (DOGM)

Date: May 11, 2000

Inspector's Signature:

#46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Peter Hess